

# Oil Field Environmental Incident Summary

**Incident:** 20160412132702      **Date/Time of Notice:** 04/12/2016 13:27

**Responsible Party:** EOG RESOURCES, INC.

**Well Operator:** EOG RESOURCES, INC.

**Well Name:** AUSTIN 436-2635H

**Field Name:** PARSHALL

**Well File #:** 32122

**Date Incident:** 4/11/2016      **Time Incident:** 18:30

**Facility ID Number:**

**County:** MOUNTRAIL

**Twp:** 154

**Rng:** 90

**Sec:** 26

**Qtr:** NW NW

**Location Description:**

**Submitted By:** Keith Kallberg

**Received By:**

**Contact Person:** Keith Kallberg  
600 17TH ST STE 1000N  
DENVER, CO 80202

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Other

**Release Contained in Dike:** Yes - On Constructed Well Site

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	1.5	Barrels	1.5	Barrels		
Brine	1.5	Barrels	1.5	Barrels		

**Other**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

NA

**Areal Extent:**

Around the wellhead.

***Potential Environmental Impacts:***

NA

***Action Taken or Planned:***

The valve was shut and the accumulator pressure was built backup to the annular bag stopping the release. Vac truck was used to remove all the free fluids from around the wellhead. Affected area will be looked at after the rig has completed the drill out to determine if further cleanup is required.

***Wastes Disposal Location:*** SWD

***Agencies Involved:***

***Updates***

---

***Date:*** 4/12/2016    ***Status:*** Reviewed - Assigned to Other Agency

***Author:*** O'Gorman, Brian

***Updated Oil Volume:***

***Updated Salt Water Volume:***

***Updated Other Volume:***

***Updated Other Contaminant***

***Notes:***

According to the report, the release remained on the constructed well site. NDIC retains oversight.